



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Supervisor 

Minerals Regulatory Program

Date of Report:

July 15, 2010

Mine Name: Quarry (Little Salt Creek Gypsum)

Operator Name: Cox Transport Incorporated

Permit number: S0230096

Inspection Date: 07/13/2010

Time: 1:40 – 2:00 PM

Inspector(s): Wayne Western

Other Participants: none

Mine Status: Active

Weather: 88 F partly sunny
skies

Elements of Inspection

	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection: This was a routine inspection

Inspection Summary:

The bond is due for escalation in August 2010, the Division will send a separate letter to the Permittee informing them that the bond will be escalated.

The Permittee did not submit the annual permit fee for 2009 and the Division will follow up with a letter.

The site appeared to be stable.

The Permittee stated in the 2008 annual permit that 1 acre had been reclaimed. If the Permittee wants to reduce the number of bonded acres then they must go through the bond release process.

Conclusions and Recommendations: Operator now is now in compliance. OGM will continue to monitor site when in the area.

Inspector's Signature _____ **Date:** _____

whw:pb

cc:

Brent C. Cox
Jerry_Mansfield@BLM.gov

O:\M023-Juab\S0230096-CoxTransportation\inspections\Insp_S0230096_07-15-2010.doc